



Office of Environmental Public Health Sciences
Washington State Department of Health
243 Israel Road Southeast, Tumwater Washington 98501

Lead Sample Collection Information

DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.

Please Note: The school district is following recommended measures to reduce children's overall exposure to lead.

School District: Kent

School Name: Fairwood Elementary

School Code: 3678

School Address: 16600 148th Ave Southeast, Renton Washington 98058

Number of Samples Collected: 55

Date Collected: 03/29/2019

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
22067	other	other		<1	04/11/2019	02542, 7:03 AM
22068	FirstDraw	Bubbler	Gym	1	04/11/2019	
22069	FirstDraw	Tap	Therapy Room	6	04/11/2019	Room is used 2x per week, low use
22070	FirstDraw	Bubbler	Room B1	1	04/11/2019	
22071	FirstDraw	Tap	Room B1	<1	04/11/2019	
22072	FirstDraw	Bubbler	Room B2	<1	04/11/2019	
22073	FirstDraw	Tap	Room B2	TB	NA	
22074	FirstDraw	Bubbler	Room B3	<1	04/11/2019	
22075	FirstDraw	Tap	Room B3	1	04/11/2019	
22076	FirstDraw	Bubbler	Room B4	1	04/11/2019	
22077	FirstDraw	Tap	Room B4	3	04/11/2019	
22078	FirstDraw	Bubbler	Room B5	<1	04/11/2019	
22079	FirstDraw	Tap	Room B5	TB	NA	
22080	FirstDraw	Bubbler	Room B6	<1	04/11/2019	
22081	FirstDraw	Tap	Room B6	<1	04/11/2019	
22082	FirstDraw	Bubbler	Room A1	3	04/11/2019	
22083	FirstDraw	Tap	Room A1	<1	04/11/2019	
22084	FirstDraw	Bubbler	Room A2	<1	04/11/2019	Sink on Left
22085	FirstDraw	Tap	Room A2	<1	04/11/2019	Sink on Left
22086	FirstDraw	Bubbler	Room A2	1	04/11/2019	Sink on Right
22087	FirstDraw	Tap	Room A2	<1	04/11/2019	Sink on Right
22088	FirstDraw	Bubbler	Room A3	1	04/11/2019	Sink on Left
22089	FirstDraw	Tap	Room A3	2	04/11/2019	Sink on Left
22090	FirstDraw	Bubbler	Room A3	1	04/11/2019	Sink on Right
22091	FirstDraw	Tap	Room A3	1	04/11/2019	Sink on Right
22092	FirstDraw	Bubbler	Room A4	1	04/11/2019	
22093	FirstDraw	Tap	Room A4	<1	04/11/2019	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
22094	FirstDraw	Bubbler	Main Office Hallway	3	04/11/2019	
22095	FirstDraw	Tap	Staff Lounge	<1	04/11/2019	
22096	FirstDraw	WaterCooler	Staff Lounge	<1	04/11/2019	
22097	FirstDraw	Tap	Staff Workroom	8	04/11/2019	No Aerator
22098	FirstDraw	Tap	Nurses Room	<1	04/11/2019	
22099	FirstDraw	Bubbler	Hallway Outside Library	TB	NA	
22100	FirstDraw	Bubbler	Room D1	2	04/11/2019	
22101	FirstDraw	Tap	Room D1	TB	NA	Water is discolored, a little bit yellow
22102	FirstDraw	Bubbler	Room D2	<1	04/11/2019	
22103	FirstDraw	Tap	Room D2	1	04/11/2019	
22104	FirstDraw	Bubbler	Room D3	<1	04/11/2019	Variable flow, difficult to collect
22105	FirstDraw	Tap	Room D3	TB	NA	
22106	FirstDraw	Bubbler	Room E1	1	04/11/2019	
22107	FirstDraw	Tap	Room E1	1	04/11/2019	
22108	FirstDraw	Bubbler	Room E2	TB	NA	Tap turned off
22109	FirstDraw	Bubbler	Room E3	TB	NA	Used this morning
22110	FirstDraw	Tap	Room E3	<1	04/11/2019	Used this morning
22111	FirstDraw	Bubbler	Room E5	<1	04/11/2019	
22112	FirstDraw	Tap	Room E5	TB	NA	
22113	FirstDraw	Bubbler	Room E4	<1	04/11/2019	
22114	FirstDraw	Tap	Room E4	1	04/11/2019	
22115	FirstDraw	Tap	Conference Room	TB	NA	

(continued)

Program ID	Sample Type	Description	Location	Lead Results (ppb)	Analysis Date	Comments
22116	FirstDraw	Bubbler	Room D6	1	04/11/2019	Some mineral deposits near mouth
22117	FirstDraw	Tap	Room D6	2	04/11/2019	
22118	FirstDraw	Bubbler	Room D5	<1	04/11/2019	
22119	FirstDraw	Tap	Room D5	1	04/11/2019	
22120	FirstDraw	Bubbler	Room D4	1	04/11/2019	Some mineral deposits around mouth of bubbler
22121	FirstDraw	Tap	Room D4	2	04/12/2019	